


# SHAD

## HONDA CRF 1000L AFRICA TWIN ADVENTURE SPORTS '18

KIT TOP HODV18ST



1 262298 x1



2 304028 x2  
M8 x 25  
DIN 7380



3 303045 x4  
Ø8



4 262299 x1



5 304104 x1  
M8 x 25  
DIN 7991




6 304032 x1  
M8 x 50  
DIN 7991



7 302024 x2  
M8



8 261072 x1  
Ø20 Ø9 x 32



9 304170 x1  
M8 x 60  
DIN 7380

### ! WARNING!

GB

Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned.

E

No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado.

D

Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist.

I

Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato.

F

Ne pas serrer les vis avant d'être sûr que le KIT est correctement monté et ajusté.

